Dart Aerospace Ltd. Tuesday, 12/20/2005 3:37:13 PM Kim Johnston User: **Process Sheet** : SKITUBE WEB : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 25331 : 10498 **Estimate Number** : D2739 Part Number P.O. Number . D2739 REV B : 12/20/2005 **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. : B LANDING GEAR : 12/20/2005 **Drawing Revision** First Issue Material : 24671 **Previous Run** : 1/15/2006 Qty: 8 Um: **Due Date** Written By Checked & Approved By ŘJ : Est. Ċ 02.11.28 Reformat Comment **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** ١, Extrusion 'I Beam' thin D26005108 1.0 8.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total Extrusion 'I Beam' thin Pick: Qty Part Number Description Batch D2600-5 Web LANDING GEAR RESOURCE 1 2.0 LANDING GEAR 1 Comment: LANDING GEAR RESOURCE 1 1-Cut D2600-5 to length as per Dwg D2739 @ ... 06-01-05 2-Drill pilot holes in web using drilling Jig DT8162 as per Dwg D2739 2 06-01-03 4-Bevel Fwd ends (1" max) of extrusion and Deburr holes and ends. O6-O7-O5 Gr 5-Use a red or black lead-free paint pen to write the part number and batch number in the middle of each $a_1 \sim 6 - 6/165$ web.

HAND FINISHING

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

4.0

3.0

QC5



Comment: INSPECT WORK TO CURRENT STEP

Each

ח	2	rt	Δ	۵	ro	e	n	2	^	_	1	.td	
v	a	16	\sim	C	ΙU	Э	u	a	L	u	L	. LU	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						:	
Part No	:	PAR #: Fault Category: N	CR: Yes	No DQ	A:	Date:	

QA: N/C Closed: ____ Date: __

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
DATE STEP		Description of NC		Corrective Action Section B	·····	Verification	A	A				
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto				

NOTE: Date & initial all entries

Date: /User: Tuesday, 12/20/2005 3:37:13 PM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SKITUBE WEB

Job Number: 25331

Part Number: D2739

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

6.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion



	Dart	Aer	osp	ace	Ltd
--	------	-----	-----	-----	-----

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								-			
		and the state of t		· · · · · · · · · · · · · · · · · · ·							
								;			

Part No:	PAR #:	Fault Category:	_ NCR: Yes No	DQA:	Date: _	
			QA: N/C	Closed:	Date: _	

NCR:			WORK OR	DER NON-CONFORMANC	E (NCR)			
10 ¹		Description of NC		Corrective Action Section B	Verification	Annessal	Ammerical	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
						•		_
							·	
				,				

NOTE: Date & initial all entries



